

AMENDMENT TO THE SPECIFICATION

Please amend paragraph 0018 as follows:

[0018] The two seams 43, 44 are the only two seams for assembling the liner 40 itself, and they are located on the lateral side thereof. That is, there are no liner assembly seams on the medial side or at the rear end of the liner. With reference to FIG. 3, in conjunction with FIG. 2, the periphery of the sole 42 of the liner 40 can be seen to include a first predetermined length that is made as one piece with the vamp 41, which length extends along the medial side of the article of footwear, whereby the seam 44 extends along the lateral side of the article of footwear and along a second predetermined length of the periphery of the sole 42.